Technical data sheet



Innolux Add Defoam

8155

Defoaming solution to improve de-aerating of Innolux products, for industrial use.

| | PRODUCT DESCRIPTION |
|------------------|--|
| Product numbers | 8155000210 |
| General | Concentrated defoaming solution to improve de-aerating and reduce the formation of foam, with broad compatibility with many Innolux products |
| Application area | Additive for Innolux base and top coats for most application methods. |

PROCESSING

Processing instructions









- Please shake / stir the product before use.
- The temperature of the product and object, and the room temperature must be at least + 15 °C.
- Innolux Add Defoam (8155) must be incorporated carefully into the hardened varnish by stirring.
- Slight thinning effect in the coating material after addition.
- Protect the product from light and sunlight!
- Paints/varnishes that have been mixed can be used as explained in the relevant technical data sheet.
- Any change in the processing sequence, environmental conditions, nonobservance of instructions or the use of products not listed may have an unfavourable effect on the result.
- Please observe our ARL 210 Working guidelines for Innolux coating systems.

Quantity to be added



Quantity to be added: 0.5% - 2% relative to the quantity of paint or varnish.

The amount added varies depending on the area of application and UV system. Please contact your sales representative.

Cleaning the working equipment



With Waschverdünner (8501) immediately after use.

1-1 IMC 8155 | 07/25 | replaces 1-0

ORDERING INFORMATION

Size of trading unit

1kg

FURTHER DETAILS

Durability / storage





Min. 6 month(s) in the original sealed containers.

Make sure the product is protected against moisture, direct sunlight, frost and high temperatures (above 30 $^{\circ}$ C).

Safety information







The product is only suitable for industrial use.

During work, wear fastened-up working clothes, protective gloves made of butyl rubber and safety goggles with side protection! If the product comes into contact with your eyes, rinse immediately with water and consult a doctor! Remove dirty, soaked clothing immediately! If the product comes into contact with your skin, wash off immediately with plenty of soap and water!

Further information on the subject of safety during transport, storage and handling as well as disposal can be found in the relevant safety data sheet. The current version can be accessed on the Internet at **www.adler-lacke.com**.